

US EPA ARCHIVE DOCUMENT

Situation Photo Log

Monday, June 25, 2012

Kalamazoo River / Enbridge Spill


Weather / River Conditions for Monday (6-25-2012)

Conditions: Sunny

Ambient Air Temperature High: 77° F

Average River Water Temperature: 77.72° F

Average River Sediment Temperature: 73.86° F



Prepared by:
Matthew Haak
START-USEPA
Situation Unit Leader



1. Morrow Lake poling team.



2. Sheen sweep boat operating on Lake Morrow.



3. Observed installation of anchors for the new containment structures within the Morrow Lake Delta.



4. Observed installation of anchors for the new containment structures within the Morrow Lake Delta.



5. Observed installation of anchors for the new containment structures within the Morrow Lake Delta.



6. MP37.5 observed crew removing curtain from the boom.



7. MP37.5 observed crew removing curtain from the boom.



8. Morrow Lake Delta anchor pole outfitted with a flashing navigational light.



9. Morrow Lake Delta flashing navigational light to be installed on the boom anchor pole.




10. E4 boat launch boom staged for deployment.



11. RI Core logging at C3.2.



12. MP8.75 LDB RI crew.



13. MP8.75 LDB RI crew.



14. Ceresco Dam portage work continued.



15. Ceresco Dam portage work continued.



16. Sheen sweep boat operating above Ceresco Dam.



17. Sheen observed above Ceresco Dam.



18. MP5.55 observed sweep boat operating along the LDB.