

US EPA ARCHIVE DOCUMENT

<b>UNIT LOG</b>		1. Incident Name Kalamazoo River/Enbridge Oil Spill	2. Date Prepared 07/02/2012	3. Time Prepared 1700
4. Unit Name/Designators Situation Unit		5. Unit Leader (Name and Position) Melinda Luetke, Planning Section Chief		6. Operational Period 0700, 06/28/12 – 0700, 07/12/12
7. Personnel Roster Assigned				
Name		ICS Position		Home Base
Matthew Haak		Situation Unit Leader		Houston, Texas
8. Activity Log				
Time	Major Events			
11:00	<p>Overflight Operational status:</p> <ul style="list-style-type: none"> <li>• Source area pond: no sheen observed, pond water levels quickly receding.</li> <li>• Frac-City: observed boom staged at the decontamination pad.</li> <li>• Former Talmadge Creek dewatering pad location: Observed soil grading occurring.</li> <li>• Confluence: sheen observed.</li> <li>• MP2.75 LDB: sheen observed.</li> <li>• MP5.25: observed sheen sweep boat operating. Observed sheen within disturbed sediment.</li> <li>• MP5.63 LDB: sheen observed. Sweep boat was observed operating in the area.</li> <li>• Ceresco Dam: sheen sweep boat observed.</li> <li>• Ceresco Dam: sheen observed along the RDB just upstream from the dam.</li> <li>• Ceresco Dam: portage work observed below the dam.</li> <li>• MP6.5 Island: sheen observed.</li> <li>• MP7.25 RDB: observed RI crew.</li> <li>• MP9.5 Historic Bridge Park observed sweep boat.</li> <li>• Paddler's Grove: observed handicap boat launch being installed.</li> <li>• MP15.75 RDB: North Mill Pond observed sheen.</li> <li>• MP17.0 RDB: sheen observed.</li> <li>• MP17.25 RDB sheen observed.</li> <li>• MP17.5 LDB: sheen observed.</li> <li>• MP21.5 LDB: sheen observed.</li> <li>• MP22.0: observed sheen sweep boat moving up stream.</li> <li>• MP26.25 LDB: sheen observed.</li> <li>• Morrow Lake Delta: observed crews installing anchors for the E4 Boom System.</li> <li>• Morrow Lake Delta: observed anchors for the E4 Boom System.</li> <li>• Morrow Lake Delta: boats agitated sediment and sheen observed.</li> <li>• Morrow Lake Delta: boom installed as part of the E4 Boom System.</li> <li>• Morrow Lake Delta: E4 Boom System.</li> <li>• Morrow Lake: observed sweep boat operating in the north cove.</li> <li>• Morrow Lake: poling crew observed in the southwest corner of the lake.</li> <li>• Morrow Lake: southeast cove sheen observed.</li> <li>• Morrow Lake: film observed.</li> </ul>			
	Additional observations: None			
15:00	Return to ICP.			
9. Prepared by (Name and Position) Matthew Haak, Situation Unit Leader, USEPA-START				