

US EPA ARCHIVE DOCUMENT

UNIT LOG		1. Incident Name Kalamazoo River/Enbridge Oil Spill	2. Date Prepared 07/03/2012	3. Time Prepared 1700
4. Unit Name/Designators Situation Unit		5. Unit Leader (Name and Position) Melinda Luetke, Planning Section Chief		6. Operational Period 0700, 06/28/12 – 0700, 07/12/12
7. Personnel Roster Assigned				
Name		ICS Position		Home Base
Matthew Haak		Situation Unit Leader		Houston, Texas
8. Activity Log				
Time	Major Events			
09:00	<p>Operational status:</p> <ul style="list-style-type: none"> • E4 Boom System: observed crews inspecting the curtain with underwater cameras. • Underwater camera being utilized by US EPA. • Underwater camera being utilized by Enbridge. • Morrow Lake Delta: observed crew installing an anchor point for the E4 Boom System Boom A. • Sheen observed in the area of the pontoon barge operating in the Morrow Lake Delta. • Observed a segment of the E4 Boom System Boom C partially installed. • Morrow Lake: poling crew observed. • Morrow Lake: observed the sheen sweep boat operating in the southeast cove of the lake. • South Mill Pond: observed sheen sweep boat operating. • MP14.75: observed a media tour. • North Mill Pond: observed sheen. • Paddler's Grove: observed handicap boat launch being installed. • Ceresco Dam portage below the dam: observed concrete work. • Ceresco Dam portage above the dam: observed concrete sidewalk installed. • Ceresco Dam: sheen observed. • Sheen sweep boat observed at C0.4 boat launch. 			
	Additional observations: None			
15:00	Return to ICP.			
9. Prepared by (Name and Position) Matthew Haak, Situation Unit Leader, USEPA-START				