

US EPA ARCHIVE DOCUMENT

<b>UNIT LOG</b>		1. Incident Name Kalamazoo River/Enbridge Oil Spill	2. Date Prepared 07/07/2012	3. Time Prepared 1700
4. Unit Name/Designators Situation Unit		5. Unit Leader (Name and Position) Melinda Luetke, Planning Section Chief		6. Operational Period 0700, 06/28/12 – 0700, 07/12/12
7. Personnel Roster Assigned				
Name		ICS Position		Home Base
Larry Rader		Situation Unit Leader		Chicago, Illinois
8. Activity Log				
Time	Major Events			
09:00	<p>Operational status:</p> <ul style="list-style-type: none"> <li>• Source area pond, sheen observed.</li> <li>• Frac-City, no activity observed.</li> <li>• Confluence, no sheen observed.</li> <li>• Observed swimmers at Saylor’s Landing.</li> <li>• Sheen observed along RDB just downstream from C0.4 boat launch, sweeper boat notified.</li> <li>• Sheen observed along southern shore downstream from C0.4 boat launch on return to Marshall, sweeper boat near northern shore was notified.</li> <li>• South peninsula above Ceresco Dam, observed sheen on upstream and downstream sides of peninsula. Sheen response crews were notified.</li> <li>• Observed crews installing control point boom at Ceresco Dam.</li> <li>• Observed crews installing control point support ropes at Ceresco Dam.</li> <li>• Sheen produced by boats installing containment boom at Ceresco Dam.</li> <li>• Observed containment boom and sheen along southern wall above Ceresco Dam.</li> <li>• Sheen observed in southwest corner above Ceresco Dam, within containment.</li> <li>• South end of Mill Pond, no sheen or activity observed.</li> <li>• North end of Mill Pond and Battle Creek spillway, no sheen observed.</li> <li>• MP 19.25 sediment trap, no sheen observed.</li> <li>• Canoers observed on river near Fort Custer.</li> <li>• Morrow Lake Delta, sheen sweeper boat observed in southwest corner of delta.</li> <li>• Sweeper boat operating in southwest corner of Morrow Lake Delta.</li> <li>• Current boom configuration at E4 control point: organic debris observed on water surface along containment boom.</li> <li>• Morrow Lake, sheen sweeper boat observed in western portion of lake. No sheen observed in lake.</li> <li>• E4 Control Point, and organic debris blowing across lake from west to east.</li> <li>• Morrow Lake Delta, containment boom staged for installation.</li> </ul>			
	Additional observations: None			
11:00	Return to ICP.			
9. Prepared by (Name and Position) Larry Rader, Situation Unit Leader, USEPA-START				