

US EPA ARCHIVE DOCUMENT

UNIT LOG		1. Incident Name Kalamazoo River/Enbridge Oil Spill	2. Date Prepared 07/13/2012	3. Time Prepared 1700
4. Unit Name/Designators Situation Unit		5. Unit Leader (Name and Position) Melinda Luetke, Planning Section Chief		6. Operational Period 0700, 07/12/12 – 0700, 07/19/12
7. Personnel Roster Assigned				
Name		ICS Position		Home Base
Larry Rader		Situation Unit Leader		Chicago, Illinois
8. Activity Log				
Time	Major Events			
0900	<p>Operational status:</p> <ul style="list-style-type: none"> • Plant staging area set up along Division Drive for Talmadge Creek tree planting activities. • Talmadge Creek: Trees unloaded and stored in shade for planting along Talmadge Creek. • Observed crew transporting debris bags from Ceresco Dam control point upstream to C0.4 boat launch. • Sheen and vegetation observed at former trestle above Ceresco Dam. • Vegetation and sheen observed along containment boom above Ceresco Dam. • Globules and sheen observed within containment above Ceresco Dam. • Recreational boaters observed near MP 15.0 upstream from the Mill Ponds. • Sheen sweep boat observed operating in the southern half of the Mill Pond. • MP 21.5 oxbow observed from Custer Road Bridge: Sheen sweep boat observed operating downstream from bridge. • Sheen sweeper boat observed downstream from MP 21.5 oxbow. • Sheen sweep boat observed operating in Morrow Lake Delta. • Morrow Lake Delta: poling crew observed moving to next poling location. • Sediment curtain inspection crew observed working at E 4.0 control point. • Recreational air boat observed along southern of Morrow Lake. 			
	Additional observations: None			
1500	Return to ICP.			
9. Prepared by (Name and Position) Larry Rader, Situation Unit Leader, USEPA-START				