

US EPA ARCHIVE DOCUMENT

<b>UNIT LOG</b>		1. Incident Name Kalamazoo River/Enbridge Oil Spill	2. Date Prepared 07/14/2012	3. Time Prepared 1700
4. Unit Name/Designators Situation Unit		5. Unit Leader (Name and Position) Melinda Luetke, Planning Section Chief		6. Operational Period 0700, 07/12/12 – 0700, 07/19/12
7. Personnel Roster Assigned				
Name		ICS Position		Home Base
Larry Rader		Situation Unit Leader		Chicago, Illinois
8. Activity Log				
Time	Major Events			
0900	<p>Operational status:</p> <ul style="list-style-type: none"> <li>• Observed trees and shrubs planted along Talmadge Creek as part of restoration activities.</li> <li>• Vegetation and sheen observed at trestle above Ceresco Dam.</li> <li>• Sheen observed along containment boom above Ceresco Dam.</li> <li>• Vegetation and sheen observed along containment boom above Ceresco Dam.</li> <li>• Observed crews removing vegetation within containment above Ceresco Dam.</li> <li>• Recreational boaters observed near MP 15.0 upstream from the Mill Ponds.</li> <li>• Fishermen observed at MP 15.75 in northern end of Mill Ponds.</li> <li>• South end of Mill Pond, no sheen observed.</li> <li>• MP 21.5: oxbow from Custer Road Bridge. No sheen observed on western side of Custer Road Bridge.</li> <li>• Sheen observed on eastern side of Custer Road Bridge, just upstream from MP 21.5 oxbow.</li> <li>• Sheen sweep boat observed operating in Morrow Lake Delta.</li> <li>• E4 Control Point, debris observed within containment.</li> <li>• Sheen sweeper boat observed operating in far western end of Morrow Lake.</li> </ul>			
	Additional observations: None			
1500	Return to ICP.			
9. Prepared by (Name and Position) Larry Rader, Situation Unit Leader, USEPA-START				