US EPA ARCHIVE DOCUMENT

US EPA ARCHIVE DOCUMENT

Situation Photo Log

Friday, July 20, 2012
Kalamazoo River / Enbridge Spill

Weather / River Conditions from Wednesday (7-19-2012):
Conditions: Sunny
Ambient Air Temperature High: 91° F
Average River Water Temperature: 82.71° F
Average River Sediment Temperature: 79.37° F



Prepared by:
Matthew Haak
START-USEPA
Situation Unit Leader

1. Morrow Lake sweep boat observed operating along the north shoreline.

2. Morrow Lake Delta observed crew performing underwater camera inspections of Boom C.

US EPA ARCHIVE DOCUMENT

3. Morrow Lake Delta poling crew observed.

4. Morrow Lake Delta observed sweep boat operating between Booms B & C.

US EPA ARCHIVE DOCUMENT

5. MP21.5 sheen observed, operations was notified.

6. MP21.5 sheen observed, operations was notified.

US EPA ARCHIVE DOCUMENT

7. MP15.5 South Mill Pond observed sweep boat operating.

8. C5 Boat Launch observed sheen ribbons floating by.

US EPA ARCHIVE DOCUMENT

9. North Mill Pond observed sheen.

10. North Mill Pond observed sheen.

US EPA ARCHIVE DOCUMENT

11. North Mill Pond observed sheen sweep boat responding to sheen sighting.

12. MP5.63 south railroad trestles observed the sheen sweep boat operating.

US EPA ARCHIVE DOCUMENT

13. MP5.63 south railroad trestles observed sheen.

14. Ceresco Dam containment boom.

US EPA ARCHIVE DOCUMENT

15. Ceresco Dam sheen collecting along the containment boom.

16. Source Area RI soil core collection work continued.

US EPA ARCHIVE DOCUMENT

17. Source Area soil core collected, sheen observed within core.

18. Source Area RI soil core work, observed a dewatering ring.

US EPA ARCHIVE DOCUMENT



19. Source Area RI soil core work, observed sheen around dewatering ring.

20. Source Area RI soil core work, observed product and sheen within dewatering ring.

US EPA ARCHIVE DOCUMENT

21. Source Area RI soil core work, observed crew installing PVC pipe into bore hole.

22. Source Area RI soil core work, observed crew installing PVC pipe into bore hole.

US EPA ARCHIVE DOCUMENT

23. Source Area RI soil core work, observed crew installing alternate dewatering ring and trash pump.

24. Source Area RI soil core work, observed crew dewatering ring with a trash pump.

US EPA ARCHIVE DOCUMENT