

US EPA ARCHIVE DOCUMENT

Situation Photo Log

Saturday, July 21, 2012

Kalamazoo River / Enbridge Spill

Prepared by:
Matthew Haak
START-USEPA
Situation Unit Leader



1. Morrow Lake observed sheen between Rowe Island and the small island E4.5 was anchored to. Operations was notified.



2. Morrow Lake observed sheen between Rowe Island and the small island E4.5 was anchored to. Operations was notified.



3. Morrow Lake Delta Boom C.



4. Morrow Lake Delta observed sheen collecting within Boom C.



5. Morrow Lake Delta Boom B.



6. Morrow Lake Delta Boom B, observed sheen collecting within boom.



7. Morrow Lake Delta observed a sweep boat operating between Booms B & C.



8. MP26.25 RDB no sheen observed.



9. MP26.0 RDB no sheen observed.



10. MP24.75 LDB no sheen observed.



11. MP23.10 RDB no sheen observed.



12. MP21.5 RDB no sheen observed.



13. Observed sweep boat operating between MP21.5 & MP30.8.



14. MP29.25 observed navigational stakes have been removed.



15. MP15.5 South Mill Pond no sheen observed.



16. MP15.5 South Mill Pond observed a sweep boat operating.



17. MP5.5 LDB observed sheen and tar glob, sweep boat was observed working in the area.



18. MP5.63 Railroad Trestles observed sheen sweep boat operating.



19. MP5.63 Railroad Trestles observed sheen and tar globs.



20. MP5.63 Railroad Trestles observed sheen and tar globs.



21. Ceresco Dam containment boom.



22. Ceresco Dam sheen collecting within the containment boom.



23. Ceresco Dam containment boom, observed the sweep boat operating.



24. Source Area RI observed crews sampling wells.



25. Source Area RI observed crews sampling wells.



26. Source Area RI observed crews sampling wells.