

US EPA ARCHIVE DOCUMENT

<b>1. Incident Name</b>	<b>2. Date Prepared</b>	<b>3. Time Prepared</b>	<b>UNIT LOG ICS 214</b>	
Kalamazoo River/Enbridge Spill	07/24/2012	1800		
<b>4. Unit Name/Designators</b>	<b>5. Unit Leader</b>		<b>6. Operational Period :</b>	
SOTF Team #7	<b>Name:</b>	Dan Capone & Joe Victory (START/US EPA)	<b>From:</b>	07/24/2012 0700
	<b>Position:</b>	Operations Section Chief	<b>To:</b>	07/24/2012 1700
<b>7. Personnel Roster Assigned</b>				
<u>Name</u>		<u>ICS Position</u>	<u>DUTY CELL</u>	
Dan Capone		Operations Section Chief		
Joe Victory		Operations Section Chief		
Dan Zahner		Field Team Lead		
Jose Aguilera		SOTF#7		
<b>8. Activity Log</b>				
<b>Activity Area</b>	<b>Morrow Lake, Morrow Lake Neck and Morrow Lake Delta</b>		<b>LAT</b>	<b>LAT</b>
			<b>Various</b>	<b>Various</b>
			(DD.MMMM)	(DD.MMMM)
<b><u>OIL OBSERVED</u></b>	<b>EXTENT OF OIL IMPACTED AREA</b>	NA		
	<b>DENSITY OF OIL /SHEEN</b>	NA		
<b>Total Collection Points</b>	<b>28 monitoring points</b>			
<b>Total Boom Deployed</b>	NA			
<b>Activity</b>	<p><b><u>START SOTF Team # 2 Activity:</u></b></p> <p>Team SOTF #7 launched out of E4 and conducted poling ops. A total of 28 poling locations were assessed in the Morrow Lake Delta.</p> <p><b><u>Poling</u></b></p> <ul style="list-style-type: none"> <li>• Morrow Lake Delta – Total: 28 with 0 Heavy, 5 Moderate, 23 Light, 0 None <ul style="list-style-type: none"> <li>○ Sheen on water surface throughout monitoring activities, some due to jet boat maneuvering.</li> <li>○ All locations passed the temperature requirement.</li> </ul> </li> </ul> <p><b><u>E4 containment System:</u></b></p> <p>Crew visually inspected all booms, however crew did not utilize under water camera.</p>			
	None			
<b>Comments</b>	Notes are in Logbook SOTF 7.			