

US EPA ARCHIVE DOCUMENT

1. Incident Name	2. Date Prepared	3. Time Prepared	UNIT LOG ICS 214	
Kalamazoo River/Enbridge Spill	07/26/2012	1900		
4. Unit Name/Designators	5. Unit Leader		6. Operational Period :	
SOTF Team #7	Name:	Dan Capone & Joe Victory (START/US EPA)	From:	07/26/2012 0700
	Position:	Operations Section Chief	To:	07/26/2012 1800
7. Personnel Roster Assigned				
Name	ICS Position		DUTY CELL	
Dan Capone	Operations Section Chief			
Joe Victory	Operations Section Chief			
Dan Zahner	Field Team Lead			
Jose Aguilera	SOTF#7			
8. Activity Log				
Activity Area	Morrow Lake, Morrow Lake Neck and Morrow Lake Delta		LAT	LAT
			Various	Various
			(DD.MMMM)	(DD.MMMM)
<u>OIL OBSERVED</u>	EXTENT OF OIL IMPACTED AREA		NA	
	DENSITY OF OIL /SHEEN		NA	
Total Collection Points	17 monitoring points			
Total Boom Deployed	NA			
Activity	<p><u>START SOTF Team # 7 Activity:</u> Team SOTF #7 launched out of E4 and conducted poling ops. A total of 28 poling locations were assessed in the Morrow Lake Delta.</p> <p><u>Poling</u></p> <ul style="list-style-type: none"> • Morrow Lake Delta – Total: 17 with 0 Heavy, 7 Moderate, 10 Light, 0 None <ul style="list-style-type: none"> ○ Some sheen due to jet boat maneuvering. ○ All locations passed the temperature requirement. ○ Team also mobilized to MP21.50 oxbow to deploy aluminum box for the agitation study. Team retrieved the downstream cylindrical sample only. Aluminum box was placed approximately 75 ft. downstream of the next set of cylindrical samples. <p><u>E4 containment System:</u> Crew utilized underwater camera to inspect boom/curtain F North and South, crew reported no adjustments needed.</p>			
	None			
Comments	Notes are in Logbook SOTF 7.			

