

US EPA ARCHIVE DOCUMENT

UNIT LOG		1. Incident Name Kalamazoo River/Enbridge Oil Spill	2. Date Prepared 07/28/2012	3. Time Prepared 1800
4. Unit Name/Designators Situation Unit		5. Unit Leader (Name and Position) Mindy Luetke, Planning Section Chief		6. Operational Period 1200, 07/26/12 – 1200, 08/2/12
7. Personnel Roster Assigned				
Name		ICS Position		Home Base
Matthew Haak		Situation Unit Aerial Field Observer		Houston, TX
8. Activity Log				
Time	Major Events			
0830	<p>Operational Observation:</p> <ul style="list-style-type: none"> • Arrived at E4 Boat Launch • Morrow Lake sheen sweep boat observed operating in the lake. • E4 Boat Launch observed sheen sweep boat staged. 			
10:30	<ul style="list-style-type: none"> • Pulled the boat out and relocated to Shady Bend Camp Ground boat launch. • MP26.25 RDB sheen observed. • MP26.0 RDB and MP24.75 LDB no sheen observed. • MP23.10 RDB very light sheen observed. 			
12:00	<ul style="list-style-type: none"> • Pulled boat and relocated to C0.4 Boat launch. • Stopped at MP21.5 Custer Bridge on the way to C0.4, no sheen observed • Stopped at MP15.5 South Mill Pond on the way to C0.4 observed ribbon of sheen. The sheen sweep boat was observed beneath Burnham Street Bridge. 			
1300	<ul style="list-style-type: none"> • MP5.3 LDB observed tar glob and sheen. • Ceresco Dam sheen sweep boat observed operating. • Ceresco Dam observed sheen and tar globs collecting at the boom. • MP5.6 RDB observed sheen and tar globs. 			
	<p>Planning Activities:</p> <ul style="list-style-type: none"> • Completed 214 • Prepared and distributed Daily Situation Unit Photolog. • Continued preparation of weekly Situation Report “SitRep” • Continued updating Organizational Staffing Gantt Chart. • Assisted with the C&G and MAC Situational Update presentation. 			
9. Prepared by (Name and Position)		Matthew Haak, Situation Unit, USEPA-START		