


US EPA ARCHIVE DOCUMENT

1. Incident Name	2. Date Prepared	3. Time Prepared	UNIT LOG ICS 214	
Kalamazoo River/Enbridge Spill	07/30/2012	17:53		
4. Unit Name/Designators	5. Unit Leader		6. Operational Period :	
SOTF Team #7	Name:	Dan Capone & Joe Victory (START/US EPA)	From:	07/30/2012 08:18
	Position:	Operations Section Chief	To:	07/30/2012 16:50
7. Personnel Roster Assigned				
Name	ICS Position		DUTY CELL	
Dan Capone	Operations Section Chief			
Joe Victory	Operations Section Chief			
Dan Zahner	Field Team Lead			
Michael Thierry	SOTF#7			
8. Activity Log				
Activity Area	Morrow Lake (MP 38.85 to 39.8) and Delta (37.2 to 37.45)		LAT	LAT
			Various	Various
			(DD.MMMM)	(DD.MMMM)
<u>OIL OBSERVED</u>	EXTENT OF OIL IMPACTED AREA	NA		
	DENSITY OF OIL /SHEEN	NA		
Total Collection Points	NA			
Total Boom Deployed	NA			
Activity	<p><u>START SOTF Team 7 Activity:</u></p> <p>START SOTF 7 and MDEQ (Susan Jones) conducted oversight documentation of Enbridge Team (Russell Platte). Team conducted poling, Secchi disk measurements and water / sediment temperature readings on Morrow Lake from MP 38.85 to 39.80 and the Morrow Delta MP 37.20 to 37.45. Morrow Lake has sixty-five monitoring points, Morrow neck has six monitoring points and the Delta has sixty-one monitoring point. All target points were above sixty degrees.</p> <p>Poling Location:</p> <p>Designated monitoring locations in Morrow lake.</p> <p>Twenty-four of the sixty-five locations were poled today. This was the start of next round of poling in the lake. The team started down at approximately MP39.8 and worked upstream towards E4.0. The first two locations on the lake were done when team lead received a phone call to move to the delta to complete the last eleven locations from last week's poling round. Once poling was completed in the delta the team resumed poling in Morrow lake.</p>			

	<p>Designated monitoring locations in delta:</p> <p>Eleven of the sixty-one locations were poled today in the delta. This completed the last poling round in the delta.</p> <p>Summary of poling results for the target locations:</p> <p>Morrow Lake had a total of twenty-four locations poled. 2 of 24 locations with nothing, 22 of 24 locations with lights, 0 of 24 locations had moderates, 0 of 24 locations had heavies.</p> <p>Delta had a total of eleven locations poled. 0 of 11 locations with nothing, 5 of 11 locations with lights, 5 of 11 locations had moderates, 1 of 11 locations had heavies.</p> <p>Weather: Morning 72 degrees, sunny and winds 1-5 mph out of the South. Afternoon 86 degrees, partly sunny with 5-10 mph out of the Southwest.</p>
<p>Health and Safety Issues</p>	
<p>Comments</p>	