

US EPA ARCHIVE DOCUMENT

<b>UNIT LOG</b>		1. Incident Name Kalamazoo River/Enbridge Oil Spill	2. Date Prepared 08/01/2012	3. Time Prepared 1800
4. Unit Name/Designators Situation Unit		5. Unit Leader (Name and Position) Mindy Luetke, Planning Section Chief		6. Operational Period 1200, 07/26/12 – 1200, 08/2/12
7. Personnel Roster Assigned				
Name		ICS Position		Home Base
Matthew Haak		Situation Unit Aerial Field Observer		Houston, TX
8. Activity Log				
Time	Major Events			
0730 0800 0900	<p><b>Operational Observation:</b></p> <ul style="list-style-type: none"> <li>• Arrived at the ICP, began the production of the Situational Photolog for the EPA C&amp;G.</li> <li>• Attended the EPA C&amp;G meeting.</li> <li>• Arrived at C0.4 Boat Launch and launched the boat.</li> <li>• MP5.0 – MP5.25 RDB area where sheen was observed.</li> <li>• MP5.25 RDB sheen and tar globs were observed.</li> <li>• MP5.35 LDB oil glob and sheen observed.</li> <li>• MP5.55 LDB sheen and tar globs observed.</li> <li>• Ceresco Dam observed crew removing debris from boom.</li> <li>• Ceresco Dam oil globs and sheen observed collecting at the boom.</li> <li>• Ceresco Dam Control Point Boom.</li> <li>• Ceresco Dam oil globs and sheen observed collecting at the boom.</li> <li>• MP5.55 RDB railroad trestles sheen observed flowing through the trestles.</li> <li>• MP5.55 RDB sheen observed.</li> <li>• MP5.63 observed the sheen sweep boat operating.</li> <li>• Ceresco Dam Control Point Boom observed sheen collecting along the boom.</li> </ul>			
10:30	<ul style="list-style-type: none"> <li>• Pulled the boat, I mobilized to the Source area to observe the RI coring work.</li> <li>• Source area RI coring team observed. Sheen observed in the ponded water.</li> </ul>			
1330	<ul style="list-style-type: none"> <li>• Boarded the helicopter for the weekly overflight.</li> <li>• MP15.5 Burnham Street Bridge no sheen observed.</li> <li>• MP15.75 observed crew launching to perform Walling Tube maintenance.</li> <li>• MP21.5 Custer Drive Bridge no sheen observed.</li> <li>• MP27.0 RDB observed shoreline restoration work.</li> <li>• Morrow Lake Delta observed boom maintenance.</li> <li>• Morrow Lake Delta observed poling crew.</li> <li>• Morrow Lake observed the sweep boat operating in the south cove.</li> <li>• Morrow Lake Delta.</li> </ul>			
	<p><b>Planning Activities:</b></p> <ul style="list-style-type: none"> <li>• Completed 214</li> <li>• Prepared and distributed Daily Situation Unit Photolog.</li> </ul>			
9.	Prepared by (Name and Position) Matthew Haak, Situation Unit, USEPA-START			