

US EPA ARCHIVE DOCUMENT

# Situation Photo Log

Friday, August 10, 2012

Kalamazoo River / Enbridge Spill

**Weather / River Conditions for Friday, August 10, 2012**

Conditions: Rain

Ambient Air Temperature High: 63° F

US EPA ARCHIVE DOCUMENT

Prepared by:  
Karen Berecz  
START-USEPA  
Situation Unit Leader



1. MP5.25 – MP5.63 LDB no sheen observed.



2. Ceresco Dam sheen observed along control point, sweep boat not warranted.



3. Ceresco Dam sheen observed along control point.



4. Ceresco Dam sheen and organic debris collecting along control point.



5. South Mill Pond no sheen observed.



6. MP15.50 LDB sheen observed, no sweep boat warranted.



7. MP21.50 RDB sweep boat observed.



8. MP26.00 RDB no sheen observed.




9. MP26.25 RDB no sheen observed.



10. MP26.75 RDB no sheen observed.



11. Morrow Lake Delta observed poling crew along Gate C.



12. Morrow Lake Delta sheen generated by poling crew along Gate C.



13. Morrow Lake no sheen observed.