

US EPA ARCHIVE DOCUMENT

UNIT LOG		1. Incident Name Kalamazoo River/Enbridge Oil Spill	2. Date Prepared 08/30/2012	3. Time Prepared 1600
4. Unit Name/Designators Situation Unit		5. Unit Leader (Name and Position) Melinda Luetke, Planning Section Chief		6. Operational Period 0700, 08/23/12 – 0700, 09/6/12
7. Personnel Roster Assigned				
Name		ICS Position		Home Base
Larry Rader		Situation Unit Leader		Chicago, Illinois
8. Activity Log				
Time	Major Events			
0915	<p>Boat safety briefing at C0.4 boat launch. Launch.</p> <p>Operational status:</p> <ul style="list-style-type: none"> • Observed sheen and tar globules along LDB across from C0.4 boat launch. • Observed sheen and tar globules in river channel near trestle at MP 5.75. • Observed sheen and tar globules within containment at control point above Ceresco Dam. • Observed crew removing debris from control point above Ceresco Dam. • Observed sediment trap survey crew operating in river channel above Ceresco Dam. • Observed sheen and petroleum odor at MP 33.1 RDB • Observed sediment trap survey crew in Delta A of Morrow Lake Delta. • Observed crews removing debris from E4.0 containment boom. • Observed crew inspecting sediment curtain and boom along northern shore of Morrow Lake Delta. • Observed sheen sweeper boat operating in southern cove of Morrow Lake. 			
	Additional observations: None			
1330	Complete ground survey at E4.0 boat launch, return to ICP.			
9. Prepared by (Name and Position) Larry Rader, Situation Unit Leader, USEPA-START				