

US EPA ARCHIVE DOCUMENT

UNIT LOG		1. Incident Name Kalamazoo River/Enbridge Oil Spill	2. Date Prepared 09/05/2012	3. Time Prepared 1630
4. Unit Name/Designators Situation Unit		5. Unit Leader (Name and Position) Isaac Aboulafia, Planning Section Chief		6. Operational Period 0700, 08/23/12 – 0700, 09/6/12
7. Personnel Roster Assigned				
Name		ICS Position		Home Base
Larry Rader		Situation Unit Leader		Chicago, Illinois
8. Activity Log				
Time	Major Events			
09:15	Boat safety briefing at C0.4 boat launch. Launch. Operational status: <ul style="list-style-type: none"> • Observed sheen and tar globules along LDB across from C0.4 boat launch. • Observed sheen and tar globules in river channel near trestle at MP 5.75. • Observed sheen and tar globules within containment at control point above Ceresco Dam. • Observed crew removing debris from control point above Ceresco Dam. • Observed sediment trap poling crew operating near MP 5.75. • Observed sweeper boat operating near MP 5.75. 			
11:00	Return to C0.4 boat launch, drive to Battle Creek Mill Ponds.			
12:00	Return to ICP.			
13:30	Meet at Brooks Field. Helicopter safety brief. Take off. <ul style="list-style-type: none"> • Observed sweeper boat operating above Ceresco Dam. • Observed sheen in river channel downstream of peninsula at MP 5.75. • Observed shoreline restoration work along LDB at Raymond Road. • No sheen or activity observed in the Mill Ponds. • Observed sediment trap survey crew and sheen sweeper boat along RDB at MP 33.0 A. • Observed debris and some sheen within containment at E4.0. • Observed sweeper pontoon boat heading toward south cove in Morrow Lake. • Observed sweeper boat operating in north cove on Morrow Lake. • Observed Morrow Lake Dam, some water observed going over spillway at dam. 			
	Additional observations: None			
14:50	Complete overflight, land at Brooks Field, return to ICP to prepare photo log & 214.			
9. Prepared by (Name and Position) Larry Rader, Situation Unit Leader, USEPA-START				