

US EPA ARCHIVE DOCUMENT

UNIT LOG		1. Incident Name Kalamazoo River/Enbridge Oil Spill	2. Date Prepared 09/08/2012	3. Time Prepared 1600
4. Unit Name/Designators Situation Unit		5. Unit Leader (Name and Position) Isaac Aboulafia, Planning Section Chief		6. Operational Period 0700, 09/6/12 – 0700, 09/13/12
7. Personnel Roster Assigned				
Name		ICS Position		Home Base
Larry Rader		Situation Unit Leader		Chicago, Illinois
8. Activity Log				
Time	Major Events			
0715	<p>Boat safety briefing at C0.4 boat launch. Launch.</p> <p>Operational status:</p> <ul style="list-style-type: none"> • Observed sheen and tar globules along LDB across from C0.4 boat launch. • Observed sheen and tar globules in river channel near trestle at MP 5.75. • Observed sheen and tar globules within containment at control point above Ceresco Dam. • Observed bathymetric survey crew installing stakes above Ceresco Dam. • Observed crew installing sediment trap at MP 33.0A RDB. • Observed rainbow sheen and strong petroleum odor at MP 33.1 RDB. • Observed Morrow Lake Delta monitoring crew conducting poling in Delta A of Morrow Lake Delta. • Observed sheen sweeper boat operating in central channel of Morrow Lake. • Windy conditions in north and south coves of Morrow Lake. No sheen observed in choppy water in coves. 			
	Additional observations: None			
1430	Complete ground survey at E4.0 boat launch, return to ICP.			
9. Prepared by (Name and Position) Larry Rader, Situation Unit Leader, USEPA-START				