

US EPA ARCHIVE DOCUMENT

UNIT LOG		1. Incident Name Kalamazoo River/Enbridge Oil Spill	2. Date Prepared 09/20/2012	3. Time Prepared 1900
4. Unit Name/Designators Situation Unit		5. Unit Leader (Name and Position) Mindy Luetke, Planning Section Chief		6. Operational Period 0700, 09/20/12 – 0700, 09/27/12
7. Personnel Roster Assigned				
Name		ICS Position		Home Base
Matthew Haak		Situation Unit Leader		Houston, TX
8. Activity Log				
Time	Major Events			
0900	<p>Boat safety briefing at C0.4 boat launch. Launch. Boat had mechanical problems, a new boat was dispatched to come take me out.</p> <p>Operational status:</p> <ul style="list-style-type: none"> • MP2.75 RDB Island sheen observed. • Source Area excavation work. • Frac-Tank City no activity observed. • MP4.4 LDB observed sheen. • Ceresco Dam observed crews performing boom maintenance. • MP11.79 back channel observed a bathymetry crew. • MP15.5 South Mill Pond no sheen observed. • MP21.5 observed a bathymetry crew. • MP23.0 observed the situation boat. • MP27.0 Shady Bend Campground boat launch observed the safety boat and sweep boat. • Morrow Lake Delta observed a bathymetry crew working along Gate B. • Morrow Lake Delta observed a bathymetry crew working along Gate B. • Morrow Lake Delta observed a bathymetry crew working along Gate C. • Morrow Lake Delta observed a Walling Tube maintenance crew. • Morrow Lake Delta MP37.75 observed a crew deploying CSD. • Morrow Lake south cove observed sheen, operations was notified. • Morrow Lake observed a Walling Tube maintenance crew. • MP36.5 RDB sheen observed. 			
	<ul style="list-style-type: none"> • Additional observations: None 			

1630	Complete ground survey at Shady Bend Campground boat launch, return to ICP.
9. Planning Functions	
<ul style="list-style-type: none">· Assisted with presentation updates.	
10. Prepared by (Name and Position)	
Matthew Haak, Situation Unit Leader, USEPA-START	