

US EPA ARCHIVE DOCUMENT

UNIT LOG		1. Incident Name Kalamazoo River/Enbridge Oil Spill	2. Date Prepared 09/24/2012	3. Time Prepared 1600
4. Unit Name/Designators Situation Unit		5. Unit Leader (Name and Position) Melinda Luetke, Planning Section Chief		6. Operational Period 0700, 09/20/12 – 0700, 09/27/12
7. Personnel Roster Assigned				
Name		ICS Position		Home Base
Larry Rader		Situation Unit Leader		Chicago, Illinois
8. Activity Log				
Time	Major Events			
0900	<p>Boat safety briefing at C0.4 boat launch. Launch.</p> <p>Operational status:</p> <ul style="list-style-type: none"> · Observed sheen and tar globules following boat agitation near MP 4.5 LDB. · Observed sheen and tar globules in river channel near trestle at MP 5.75. · Observed sheen and tar globules within containment at control point above Ceresco Dam. · Observed sediment trap at MP 10.75 LDB, no sheen observed. · Observed Mill Ponds. Sheen observed in north end of Mill Ponds near culverts following agitation of sediment by boat. · Observed poling and bathymetry crews operating along northern and southern shorelines of Morrow Lake Delta. · Observed sheen sweeper boat operating in northern cove of Morrow Lake. · Observed continued scraping and backfilling activities at Source Area (MP 0.0). 			
	Additional observations: None			
1540	Return to ICP.			
9. Prepared by (Name and Position) Larry Rader, Situation Unit Leader, USEPA-START				