

US EPA ARCHIVE DOCUMENT

UNIT LOG		1. Incident Name Kalamazoo River/Enbridge Oil Spill	2. Date Prepared 10/04/2012	3. Time Prepared 1700
4. Unit Name/Designators Situation Unit		5. Unit Leader (Name and Position) Melinda Leutke, Planning Section Chief		6. Operational Period 0700, 10/04/2012 – 0700, 10/11/2012
7. Personnel Roster Assigned				
Name		ICS Position		Home Base
Larry Rader		Situation Unit Leader		Chicago, Illinois
8. Activity Log				
Time	Major Events			
1300	<p>Boat safety meeting at C0.4 boat launch. Launch.</p> <p>MP 4.5 Lily Pad area, sheen observed following boat agitation of sediment.</p> <p>MP 5.25 LDB, sheen sweeper boat observed operating along LDB.</p> <p>MP 5.25 LDB, sheen and tar globules observed along LDB.</p> <p>MP 5.63 RDB, sheen and tar globules observed upstream of trestle near pyramids.</p> <p>MP 5.63 RDB, sheen ribbons observed along former utility poles at trestle.</p> <p>MP 5.75, sheen observed along Ceresco containment boom following agitation by boat.</p> <p>Sheen ribbons and tar globules observed along Ceresco Dam control point.</p> <p>Sheen and debris within containment at Ceresco Dam.</p> <p>MP 15.5 south Mill Pond. Sheen and tar globules observed.</p>			
1500	Finish up inspections at E4.0 boat launch. Return to ICP.			
9. Prepared by (Name and Position) Larry Rader, Situation Unit Leader, USEPA-START				