

US EPA ARCHIVE DOCUMENT

Situation Photo Log

Saturday, October 13, 2012

Kalamazoo River / Enbridge Spill

Water / Sediment Temperatures

Location	Water Temp. (°F)	Sediment Temp. (°F)
C0.4 Boat Launch Gauge	47.01	49.61

US EPA ARCHIVE DOCUMENT

Prepared by:
Matthew Haak
START-USEPA
Situation Unit Leader



1. C0.4 Boat Launch water level gauge sheen observed.



2. C0.4 Boat Launch observed sheen and tar globs.



3. C0.4 Boat Launch observed sheen and tar globs..



4. C0.4 Boat Launch observed sheen and tar globs.



5. C0.4 Boat Launch observed sheen and tar globs.



6. MP5.63 LDB no sheen observed.



7. Ceresco Dam control point boom.



8. Sheen observed collecting along the control point boom.



9. Sheen observed collecting along the control point boom.



10. MP5.55N no sheen observed.



11. MP5.0 RDB sheen and tar glob observed.



12. MP4.5 no sheen observed.