

US EPA ARCHIVE DOCUMENT

Situation Photo Log

Monday, October 22, 2012

Kalamazoo River / Enbridge Spill

Water / Sediment Temperatures

Location	Water Temp. (°F)	Sediment Temp. (°F)
C0.4 Boat Launch Gauge	54.76	55.12
Ceresco Dam Control Point Boom	53.86	57.31
C3.2 Boat Launch Gauge	54.17	55.27
C5 Boat Launch Gauge	54.65	55.04
E4 Boat Launch Gauge	56.98	56.10

Prepared by:
Matthew Haak
START-USEPA
Situation Unit



1. MP5.0 - MP5.55 LDB area where sheen and tar globs were observed.



2. MP5.0 LDB sheen and tar globs were observed.



3. MP5.25 LDB sheen and tar globs were observed.



4. MP5.35 LDB sheen and tar globs were observed.



5. MP5.45 LDB sheen and tar globs were observed.



6. MP5.63 LDB area where and sheen and tar globs were observed.



7. MP5.63 LDB area where and sheen and tar globs were observed.



8. Ceresco Dam Control Point Boom observed sheen and tar globs collecting along the boom.



9. Ceresco Dam Control Point Boom observed sheen and tar globs collecting along the boom.



10. Ceresco Dam control point boom observed a crew removing debris from the control point boom.



11. Ceresco Dam upstream end of the control point boom observed sheen collecting along the boom.



12. MP4.75 LDB area where sheen was observed.



13. MP4.75 LDB area where sheen was observed.



14. MP8.5 LDB observed the RI crew working.



15. MP10.75 Sediment trap.



16. MP10.75 Sediment trap sheen and tar glob observed.



17. MP14.5 LDB Area where sheen was observed.




18. MP14.5 LDB sheen was observed.



19. MP15.5 South Mill Pond ribbons of sheen were observed.



20. MP15.5 South Mill Pond ribbons of sheen and tar globs were observed.



21. MP15.5 South Mill Pond ribbons of sheen and tar globs were observed.



22. MP15.0 LDB South Mill Pond area where ribbons of sheen were observed.



23. MP15.0 LDB South Mill Pond area where ribbons of sheen were observed.



24. MP11.79 Back channel sediment trap.



25. MP11.79 Back channel sediment trap.



26. Morrow Lake E4 Boat launch sheen observed.



27. Morrow Lake Delta Gate F observed sheen collecting along the boom.



28. Morrow Lake Delta Gate E observed sheen collecting along the boom.



29. Morrow Lake Delta observed the poling team.



30. MP36.5 Boat agitated sheen.