

US EPA ARCHIVE DOCUMENT

UNIT LOG		1. Incident Name Kalamazoo River/Enbridge Oil Spill	2. Date Prepared 10/24/2012	3. Time Prepared 1700
4. Unit Name/Designators Situation Unit		5. Unit Leader (Name and Position) Melinda Leutke, Planning Section Chief		6. Operational Period 0700, 10/18/2012 – 0700, 10/25/2012
7. Personnel Roster Assigned				
Name		ICS Position		Home Base
Matthew Haak		Situation Unit Leader		Houston, TX
8. Activity Log				
Time	Major Events			
0900	<ul style="list-style-type: none"> • Boat safety meeting at C0.4 boat launch. Launch. • MP5.25 LDB area where sheen and tar globs were observed. • MP5.35 LDB sheen and tar globs were observed. • MP5.45 LDB sheen and tar globs observed. • MP5.63 LDB sheen and tar globs observed. • Ceresco Dam Control Point Boom observed sheen and tar globs collecting along the boom. • MP5.63 RDB sheen and tar globs observed. • MP5.55 RDB sheen observed. • MP5.15 RDB sheen observed. • Morrow Lake Delta Gate E observed crews inspecting containment curtain. • Morrow Lake observed a poling crew. • Morrow Lake south cove sheen observed. • Morrow Lake Delta Gate F sheen observed along the boom. • MP36.5 observed a hunter exiting the wetland area. 			
1600	Finish up inspections at E4 boat launch. Return to ICP.			
9. Prepared by (Name and Position) Matthew Haak, Situation Unit Leader, USEPA-START				