

US EPA ARCHIVE DOCUMENT

UNIT LOG		1. Incident Name Kalamazoo River/Enbridge Oil Spill	2. Date Prepared 10/25/2012	3. Time Prepared 1700
4. Unit Name/Designators Situation Unit		5. Unit Leader (Name and Position) Melinda Leutke, Planning Section Chief		6. Operational Period 0700, 10/25/2012 – 0700, 11/1/2012
7. Personnel Roster Assigned				
Name		ICS Position		Home Base
Matthew Haak		Situation Unit Leader		Houston, TX
8. Activity Log				
Time	Major Events			
0900	<ul style="list-style-type: none"> • Boat safety meeting at C0.4 boat launch. Launch. • MP5.35 LDB spontaneous sheen observed. • MP5.45 LDB spontaneous sheen observed. • MP5.63 LDB spontaneous sheen observed. • Ceresco Dam observed a crew preparing to remove debris from the control point boom. • Ceresco Dam observed sheen and tar globs collecting along the boom. • MP5.55 RDB area where spontaneous sheen and tar globs observed. • MP5.25 RDB spontaneous sheen and tar globs observed. 			
11:30	<ul style="list-style-type: none"> • Returned to the ICP 			
13:30	<ul style="list-style-type: none"> • Boarded the helicopter. • Source area sheen observed. • Frac-Tank City observed standing water. • MP7.75 I observed an RI crew. • MP10.0 LDB observed an RI crew. • MP19.25 Sediment Trap observed sheen collecting. • Morrow Lake Delta observed a crew removing debris from Gate B. • Morrow Lake Delta observed a poling crew. 			
1500	Finish finished the overflight. Return to ICP.			
9. Prepared by (Name and Position) Matthew Haak, Situation Unit Leader, USEPA-START				