

US EPA ARCHIVE DOCUMENT

Situation Photo Log

Monday, November 5, 2012

Kalamazoo River / Enbridge Spill

Water / Sediment Temperatures

Location	Water Temp. (°F)	Sediment Temp. (°F)
C3.2 Boat Launch Gauge	41.30	44.70
E4 Boat Launch Gauge	44.57	45.49

Prepared by:
Matthew Haak
START-USEPA
Situation Unit



1. Ceresco Dam control point, sheen and debris observed.



2. Ceresco Dam control point, sheen and debris observed.



3. MP10.0 RDB overbank observed RI crew.



4. E4 Boat Launch observed Walling Tube buoys and anchors removed from the Lake and Delta.



5. MP36.5 observed a crew removing a Walling Tube anchor.



6. Observed fish shocking at the 35th Street Bridge.