

US EPA ARCHIVE DOCUMENT

UNIT LOG		1. Incident Name Kalamazoo River/Enbridge Oil Spill	2. Date Prepared 11/7/2012	3. Time Prepared 1800
4. Unit Name/Designators Situation Unit		5. Unit Leader (Name and Position) Melinda Leutke, Planning Section Chief		6. Operational Period 0700, 11/5/2012 – 0700, 11/27/2012
7. Personnel Roster Assigned				
Name		ICS Position		Home Base
Matthew Haak		Situation Unit Leader		Houston, TX
8. Activity Log				
Time	Major Events			
08:00	<ul style="list-style-type: none"> • Internal Command and General Staff meeting • Worked on the ice tracking spreadsheet. 			
12:00	<ul style="list-style-type: none"> • Boat safety meeting at E0.4 boat launch. Launch. • Chris, Alex, Gary and I inspected the E4 booming system. • Relocated to C5 Mill Ponds. • Chris, Alex, Gary and I inspected the Mill Ponds impoundment. • Relocated to C0.4 boat launch. • Chris, Alex, Gary and I inspected the Ceresco Dam Impoundment. • MP5.35 LDB sheen and tar globs observed • MP5.45 LDB sheen and tar globs observed. • MP5.55 LDB sheen and tar globs observed. • Ceresco Dam observed sheen collecting along the control point boom. 			
16:00	Returned to Boat Launch C0.4. Return to ICP.			
9. Prepared by (Name and Position) Matthew Haak, Situation Unit Leader, USEPA-START				