

US EPA ARCHIVE DOCUMENT

Situation Photo Log

Tuesday, November 13, 2012

Kalamazoo River / Enbridge Spill

Water / Sediment Temperatures

Location	Water Temp. (°F)	Sediment Temp. (°F)
C0.4 Boat Launch Gauge	44.94	47.72
Ceresco Dam Control Point Boom	44.95	50.51
C3.2 Boat Launch Gauge	44.43	48.03
C5 Boat Launch Gauge	44.70	45.95
E4 Boat Launch Gauge	46.69	47.86



1. MP5.20 LDB sheen observed after a large carp swam away.



2. Ceresco Dam control point boom observed sheen and debris collecting along the boom.



3. MP5.25 RDB area where sheen and tar globs were observed.



4. MP5.25 RDB sheen and tar globs observed.



5. MP5.25 RDB sheen and tar globs observed.



6. MP4.75 LDB area where sheen and tar globs were observed.



7. MP4.75 LDB sheen and tar globs observed.



8. MP10.25 RDB observed an RI crew.



9. MP10.25 RDB observed an RI crew.



10. MP15.75 RDB North Mill Pond area where sheen and tar globs were observed.



11. MP15.75 RDB observed sheen and tar globs.



12. MP15.75 RDB observed sheen and tar globs.



13. MP15.5 LDB area where sheen and tar globs were observed.



14. MP15.5 LDB sheen and tar globs observed.



15. MP15.5 LDB sheen and tar globs observed.



16. MP15.25 LDB sheen and tar globs observed.



17. MP15.0 LDB side channel sheen and tar globs observed.



18. MP15.0 LDB side channel sheen and tar globs observed.



19. MP14.5 LDB area where sheen and tar globs were observed.



20. MP14.5 LDB sheen and tar globs observed.




21. Morrow Lake north cove area where sheen and tar globs were observed.



22. Morrow Lake north cove sheen and tar globs observed.



23. Morrow Lake Delta Gate F observed sheen and tar globs collecting along the boom.



24. Morrow Lake Delta Gate F observed sheen and tar globs collecting along the boom.



25. Morrow Lake Delta Gate E observed sheen and tar globs collecting along the boom.



26. Morrow Lake Delta Gate E observed sheen and tar globs collecting along the boom.



27. Morrow Lake Delta Bathymetry survey transit.



28. Morrow Lake Delta Gate C observed a Bathymetry team.



29. Morrow Lake Delta Gate C observed a Bathymetry team.



30. Morrow Lake Delta Gate C observed a crew inspecting the curtain.