

US EPA ARCHIVE DOCUMENT

<b>UNIT LOG</b>		1. Incident Name Kalamazoo River/Enbridge Oil Spill	2. Date Prepared 11/14/2012	3. Time Prepared 1800
4. Unit Name/Designators Situation Unit		5. Unit Leader (Name and Position) Melinda Leutke, Planning Section Chief		6. Operational Period 0700, 11/5/2012 – 0700, 11/27/2012
7. Personnel Roster Assigned				
Name		ICS Position		Home Base
Matthew Haak		Situation Unit Leader		Houston, TX
8. Activity Log				
Time	Major Events			
08:00	<ul style="list-style-type: none"> <li>• Internal Command and General Staff meeting</li> </ul>			
10:00	<ul style="list-style-type: none"> <li>• Boarded the helicopter for the weekly overflight.</li> <li>• Source area, observed the new line 6B work.</li> <li>• Talmadge Creek, observed the new line 6B work.</li> <li>• Frac-Tank decontamination pad no activity observed.</li> <li>• MP10.75 observed an RI crew.</li> <li>• MP11.75 back water channel observed sheen.</li> <li>• MP23.5 observed a sweep boat operating.</li> <li>• MP33.0 A&amp;B sediment traps observed a crew setting a monument.</li> <li>• Morrow Lake Delta observed the Bathymetry team at Gate D.</li> <li>• Morrow Lake Delta observed the Bathymetry team at Gate E.</li> </ul>			
12:00	<ul style="list-style-type: none"> <li>• Boat safety meeting at C0.4 boat launch. Launch.</li> <li>• Ceresco Dam control point boom observed sheen and tar globs collecting along the boom.</li> <li>• Morrow Lake Delta Gate E observed a crew inspecting the curtain.</li> <li>• MP5.0 – 5.63LDB no sheen observed.</li> <li>• MP4.5 LDB no sheen observed.</li> <li>• Morrow Lake Delta no sheen observed.</li> </ul>			
16:00	Returned to Boat Launch E4. Return to ICP.			
9. Prepared by (Name and Position) Matthew Haak, Situation Unit Leader, USEPA-START				