

US EPA ARCHIVE DOCUMENT

| | | | | |
|---|--|--|--------------------------------|---|
| UNIT LOG | | 1. Incident Name Kalamazoo River/Enbridge Oil Spill | 2. Date Prepared 11/28/2012 | 3. Time Prepared 1800 |
| 4. Unit Name/Designators Situation Unit | | 5. Unit Leader (Name and Position) Melinda Luetke, Planning Section Chief | | 6. Operational Period 0700, 11/27/2012 – 0700, 12/10/2012 |
| 7. Personnel Roster Assigned | | | | |
| Name | | ICS Position | | Home Base |
| Larry Rader | | Situation Unit Leader | | Chicago, IL |
| 8. Activity Log | | | | |
| Time | Major Events | | | |
| 09:30 | <ul style="list-style-type: none"> Arrived at C0.4 boat launch. No sheen observed in vicinity of trestle above Ceresco Dam. Bank ice observed along LDB and RDB on upstream and downstream sides of trestle. | | | |
| 12:30 | <ul style="list-style-type: none"> Bank ice observed along LDB near portage on upstream side of Ceresco Dam No sheen, some debris observed within Ceresco Dam containment boom. Ice observed in debris along with surface ice fragments at boom. Ceresco Dam control point, observed bathymetry survey crews operating along LDB below trestle and RDB above Dam. | | | |
| 11:30 | <ul style="list-style-type: none"> Morrow Lake Delta, boom anchors remain in place. | | | |
| 13:00 | <ul style="list-style-type: none"> Ice observed in southern cove on Morrow Lake. E4.0 boat launch, large pontoon boat arrives and is delivered via flatbed semi to boat launch. Crews unload pontoon and stage it at boat launch for boom anchor removal. | | | |
| 14:30 | Returned to ICP to prepare for 15:00 Operations meeting. | | | |
| 9. Prepared by (Name and Position) Larry Rader, Situation Unit Leader, USEPA-START | | | | |