

US EPA ARCHIVE DOCUMENT

UNIT LOG		1. Incident Name Kalamazoo River/Enbridge Oil Spill	2. Date Prepared 12/08/2012	3. Time Prepared 1700
4. Unit Name/Designators Situation Unit		5. Unit Leader (Name and Position) Melinda Luetke, Planning Section Chief		6. Operational Period 0700, 11/27/2012 – 0700, 12/10/2012
7. Personnel Roster Assigned				
Name		ICS Position		Home Base
Matthew Haak		Situation Unit Leader		Houston
8. Activity Log				
Time	Major Events			
0830	<ul style="list-style-type: none"> • Arrived at E0.4 boat launch. • Morrow Lake observed a sweep boat in the north cove. • Morrow Lake no sheen observed in the north or south coves. • MP36.5 RDB no sheen observed. • MP28.25 Sediment trap observed bathymetry teams. • MP28.25 Sediment trap observed deployed snare boom to collect sheen and tar globs generated by the bathymetry teams. • MP19.25 Sediment trap observed a bathymetry team. • MP15.25 South Mill Pond no sheen observed. • MP5.63 LDB sheen and tar globs observed. • Ceresco Dam control point boom observed sheen and tar globs collecting along the boom. 			
1330	Returned to ICP.			
9. Prepared by (Name and Position) Matthew Haak, Situation Unit Leader, USEPA-START				