

US EPA ARCHIVE DOCUMENT

<b>UNIT LOG</b>		1. Incident Name Kalamazoo River/Enbridge Oil Spill	2. Date Prepared 12/10/2012	3. Time Prepared 1700
4. Unit Name/Designators Situation Unit		5. Unit Leader (Name and Position) Melinda Luetke, Planning Section Chief		6. Operational Period 0700, 11/27/2012 – 0700, 12/10/2012
7. Personnel Roster Assigned				
Name		ICS Position		Home Base
Matthew Haak		Situation Unit Leader		Houston
8. Activity Log				
Time	Major Events			
0800	<ul style="list-style-type: none"> <li>• Attended the internal C&amp;G meeting</li> </ul>			
0900	<ul style="list-style-type: none"> <li>• Arrived at C0.4 boat launch.</li> <li>• Ceresco Dam impoundment observed a bathymetry team.</li> <li>• MP5.55 RDB sheen and tar globs observed.</li> <li>• MP11.75 RDB observed an RI crew.</li> <li>• MP15.25 South Mill Pond no sheen observed.</li> <li>• MP15.65 LDB sheen and tar globs observed.</li> <li>• MP33.0 A Sediment trap observed a bathymetry team.</li> <li>• MP33.0 B Sediment trap observed a bathymetry team.</li> <li>• MP28.25 Sediment trap observed a bathymetry team.</li> <li>• MP28.25 Snare boom remains across the channel to collect sheen and tar globs generated by the bathymetry team.</li> <li>• Morrow Lake North Cove observed sheen and tar globs.</li> <li>• MP37.5 LDB Morrow Lake Delta sheen was observed.</li> </ul>			
16:00	Returned to ICP.			
9. Prepared by (Name and Position) Matthew Haak, Situation Unit Leader, USEPA-START				