

US EPA ARCHIVE DOCUMENT

UNIT LOG		1. Incident Name Kalamazoo River/Enbridge Oil Spill	2. Date Prepared 12/11/2012	3. Time Prepared 1700
4. Unit Name/Designators Situation Unit		5. Unit Leader (Name and Position) Melinda Luetke, Planning Section Chief		6. Operational Period 0700, 12/10/2012 – 0700, 12/22/2012
7. Personnel Roster Assigned				
Name		ICS Position		Home Base
Matthew Haak		Situation Unit Leader		Houston
8. Activity Log				
Time	Major Events			
0800	<ul style="list-style-type: none"> Attended the internal C&G meeting 			
1000	<ul style="list-style-type: none"> Arrived Brooks field and boarded the helicopter. Source Area observed the pipeline installation preparation work continuing at the source area and across Talmadge Creek. Frac Tank City, no decon operations observed. Ceresco Dam impoundment observed a bathymetry crew. MP5.63 LDB & RDB observed ice forming. Observed a crew at the Ceresco Dam dredge pad. MP10.4 RDB Sediment Trap observed ice beging to form. MP10.5 LDB Sediment Trap observed ice beging to form. MP12.25 LDB observed an RI crew. North and South Mill Ponds observed ice forming. MP15.25 South Mill Pond no sheen observed. MP21.5 Sediment Trap observed a bathymetry crew. MP26.25 Sediment Trap observed a bathymetry crew. MP33.0A Sediment Trap observed a bathymetry crew.. MP33.0B Sediment Trap observed a bathymetry crew. 			
1200	<ul style="list-style-type: none"> Poling crew observed below Morrow Lake Dam. Arrived at C0.4 Boat launch, boat had mechanical issues and would be down the rest of the day. 			
12:30	Returned to ICP.			
9. Prepared by (Name and Position) Matthew Haak, Situation Unit Leader, USEPA-START				