

US EPA ARCHIVE DOCUMENT

UNIT LOG		1. Incident Name Kalamazoo River/Enbridge Oil Spill	2. Date Prepared 12/28/2012	3. Time Prepared 1700
4. Unit Name/Designators Situation Unit		5. Unit Leader (Name and Position) Melinda Luetke, Planning Section Chief		6. Operational Period 0700, 12/24/2012 – 0700, 1/14/2013
7. Personnel Roster Assigned				
Name		ICS Position		Home Base
Larry Rader		Situation Unit Leader		Chicago, IL
8. Activity Log				
Time	Major Events			
0900	<ul style="list-style-type: none"> • Morrow Lake Delta, no sheen or ice observed. • E4.0 boat launch. Mild snowfall observed, river channel through delta is open water with sparse ice. Western end of lake and north and south coves appear to be covered with ice/snow. • MP 27.0 Shady Bend Campground, minor bank ice observed. • MP21.5 RDB, no sheen or ice observed in back channel. • MP15. 5 Mill Ponds, eastern portions of Mill Ponds are covered with ice/snow. Frazil ice observed forming in river channel below Burnham Street Bridge. • Ceresco Dam, ice & snow observed along both RDB and LDB. Some ice & snow observed flowing through river channel. No sheen observed. • MP 5.63 trestle, ice observed along both banks. Low visibility due to snowfall. 			
1500	Returned to ICP.			
9. Prepared by (Name and Position) Larry Rader, Situation Unit Leader, USEPA-START				