

US EPA ARCHIVE DOCUMENT

<b>UNIT LOG</b>		1. Incident Name Kalamazoo River/Enbridge Oil Spill	2. Date Prepared 12/29/2012	3. Time Prepared 1700
4. Unit Name/Designators Situation Unit		5. Unit Leader (Name and Position) Melinda Luetke, Planning Section Chief		6. Operational Period 0700, 12/24/2012 – 0700, 1/14/2013
7. Personnel Roster Assigned				
Name		ICS Position		Home Base
Larry Rader		Situation Unit Leader		Chicago, IL
8. Activity Log				
Time	Major Events			
0900	<ul style="list-style-type: none"> <li>• L. Rader meets Oliver Webb with SWAT at C0.4 boat launch. No significant ice observed in vicinity of boat launch.</li> <li>• Ceresco Dam, ice in vicinity of trestle and impoundment has receded from yesterday's observations. River channel is open.</li> <li>• E4.0 boat launch, hunters observed deploying duck/goose decoys near island just south of E4.0 boat launch.</li> <li>• Morrow Lake Delta, no sheen or ice observed.</li> <li>• E4.0 boat launch. Ice appears to have receded in the south cove. The western end of the lake and the north cove appear to still be covered with ice/snow.</li> <li>• MP15. 5 Mill Ponds, eastern portions of Mill Ponds are covered with ice/snow. No sheen or frazil ice observed in river channel.</li> </ul>			
1200	Returned to ICP.			
9. Prepared by (Name and Position) Larry Rader, Situation Unit Leader, USEPA-START				