

US EPA ARCHIVE DOCUMENT

UNIT LOG		1. Incident Name Kalamazoo River/Enbridge Oil Spill	2. Date Prepared 01/16/2013	3. Time Prepared 1500
4. Unit Name/Designators Situation Unit		5. Unit Leader (Name and Position) Melinda Luetke, Planning Section Chief		6. Operational Period 0700, 1/14/2013 – 0700, 1/28/2013
7. Personnel Roster Assigned				
Name		ICS Position		Home Base
Matthew Haak		Situation Unit Leader		Houston, TX
8. Activity Log				
Time	Major Events			
0800	<ul style="list-style-type: none"> • Attended the EPA C&G meeting. 			
1000	<ul style="list-style-type: none"> • Arrived at Brooks Field and boarded the helicopter. • Source Area, observed a crew collecting soil cores. • Frac Tank City, no decon operations observed. • Ceresco Dam impoundment observed ice. • Ceresco Dam impoundment, observed bank ice forming. • MP10.4 & MP10.5 Sediment Traps observed the sediment traps frozen over. • MP10.75 Sediment Trap observed ice conditions. • MP11.78 Sediment Trap observed ice conditions. • MP14.75 Sediment Trap ice conditions. • South Mill Pond and North Mill Pond observed ice forming. • MP19.15 LDB observed an RI crew. • MP19.25 Sediment Trap observed ice conditions. • MP21.5 Sediment Trap observed ice conditions. • MP26.0 Sediment Trap observed ice conditions. • MP28.25 Sediment Trap observed ice conditions. • MP30.8 Sediment Trap observed ice conditions. • MP33.0 A Sediment Trap ice conditions. • MP33.0 B Sediment Trap observed ice conditions. • Morrow Lake Delta observed ice forming within the delta. • Morrow Lake observed the lake frozen over. 			
1200	Returned to ICP.			
9. Prepared by (Name and Position) Matthew Haak, Situation Unit Leader, USEPA-START				