

US EPA ARCHIVE DOCUMENT

UNIT LOG		1. Incident Name Kalamazoo River/Enbridge Oil Spill	2. Date Prepared 01/21/2013	3. Time Prepared 1500
4. Unit Name/Designators Situation Unit		5. Unit Leader (Name and Position) Melinda Luetke, Planning Section Chief		6. Operational Period 0700, 1/14/2013 – 0700, 1/28/2013
7. Personnel Roster Assigned				
Name		ICS Position		Home Base
Matthew Haak		Situation Unit Leader		Houston, TX
8. Activity Log				
Time	Major Events			
0900	<ul style="list-style-type: none"> • Arrived at the C0.4 Boat Launch and met up with my Enbridge counterpart. • MP5.63 Railroad Trestles observed ice forming, center channel remains open with sheet ice flowing in the river. • MP5.85 observed ice forming, center channel remains open with sheet ice flowing in the river. • C3.2 Pole Barn observed core logging operations. • C3.2 Boat launch observed bank ice forming and sheet ice flowing in the river. • MP15.25 South Mill Pond observed the South Mill Pond frozen over and sheet ice flowing in the river. • MP15.25 bank ice forming and sheet ice flowing in the river • MP19.25 observed bank ice forming and sheet ice flowing in the river. • MP19.25 RDB observed the RI crew. • MP21.5 observed the oxbow frozen over and sheet ice flowing in the river. • MP21.5 observed sheet ice flowing in the river. • E2 Boat launch observed bank ice forming and sheet ice flowing in the river. • E0.5 Boat Launch observed sheet ice flowing in the river. • Morrow Lake observed the lake completely frozen over. • Morrow Lake Delta/Morrow Lake Neck observed frozen over. • Morrow Lake Delta observed the delta nearly frozen over. 			
1230	Returned to ICP.			
9. Prepared by (Name and Position) Matthew Haak, Situation Unit Leader, USEPA-START				