

US EPA ARCHIVE DOCUMENT

UNIT LOG		1. Incident Name Kalamazoo River/Enbridge Oil Spill	2. Date Prepared 01/23/2013	3. Time Prepared 1500
4. Unit Name/Designators Situation Unit		5. Unit Leader (Name and Position) Melinda Luetke, Planning Section Chief		6. Operational Period 0700, 1/14/2013 – 0700, 1/28/2013
7. Personnel Roster Assigned				
Name		ICS Position		Home Base
Matthew Haak		Situation Unit Leader		Houston, TX
8. Activity Log				
Time	Major Events			
0900	<ul style="list-style-type: none"> • Attended the EPA C&G meeting. 			
09:45	<ul style="list-style-type: none"> • Ceresco Dam impoundment observed the impoundment completely frozen over. • C3.2 Pole Barn observed core logging operations. • C3.2 Boat launch observed the river backing up and flooding into the overbank. • MP10.35 LDB observed the river backing up and flooding into the overbank. • MP15.25 South Mill Pond observed the South Mill Pond frozen over. • MP15.25 observed the river completely frozen over. • MP15.5 observed the river completely frozen over. • MP15.75 North Mill Pond culverts, observed the river completely frozen over. • MP20.75 RDB observed the RI crew. • MP21.5 observed the oxbow and the majority of the river frozen over. • E2 Boat launch observed bank ice forming and sheet ice flowing in the river. • MP27.0 E0.5 Boat launch observed bank ice forming and sheet ice flowing in the river. Observed the river level slightly elevated. • Morrow Lake observed frozen over. • Morrow Lake Delta/Morrow Lake Neck observed frozen over. • Morrow Lake Delta observed frozen over. 			
1200	Returned to ICP.			
9. Prepared by (Name and Position) Matthew Haak, Situation Unit Leader, USEPA-START				