

US EPA ARCHIVE DOCUMENT

UNIT LOG	1. Incident Name Kalamazoo River/Enbridge Oil Spill	2. Date Prepared 02/20/2013	3. Time Prepared 1600
4. Unit Name/Designators Situation Unit	5. Unit Leader (Name and Position) Melinda Luetke, Planning Section Chief		6. Operational Period 0700, 2/11/2013 – 0700, 2/25/2013
7. Personnel Roster Assigned			
Name		ICS Position	Home Base
Matthew Haak		Situation Unit Leader	Houston, TX
8. Activity Log			
Time	Major Events		
0900	Attended the EPA C&G meeting.		
1000	- Arrived at Brooks Field and boarded the helicopter. - C0.4 Boat launch river conditions observed. - MP5.75 Ceresco Dam impoundment river conditions observed. - MP5.63 Ceresco Dam impoundment river conditions observed. - Ceresco Dam impoundment river conditions observed. - C3.2 Pole Barn observed core logging. - C3.2 Observed river conditions. - MP15.25 South Mill Pond river icing conditions observed. - MP15.75 North Mill Pond river icing conditions observed. - MP21.5 River conditions observed. - MP26.25 RDB observed the RI crew. - MP26.0 Sediment trap river conditions. - MP27.0 Shady Bend Campground river conditions observed. - E2 Boat launch observed river conditions. - Morrow Lake water conditions. - Morrow Lake Delta Neck river conditions observed. - Morrow Lake Delta river conditions observed. - MP10.5 Sediment trap icing conditions observed. - MP10.4 Sediment trap icing conditions observed.		
1400	Returned to ICP.		
9. Prepared by (Name and Position) Matthew Haak, Situation Unit Leader, USEPA-START			