

**SITE PHOTOGRAPHS
REMEDIAL ACTION FOR OPERABLE UNIT 2
RESIDENTIAL SURFACE SOILS
TAR CREEK SUPERFUND SITE, OTTAWA COUNTY, OKLAHOMA**



Excavation of Contaminated Soils From A Residential Area



Remediated Property - Note the chat pile in the background and the recently placed sod and limestone driveway in the foreground.

SITE PHOTOGRAPHS
REMEDIAL ACTION FOR OPERABLE UNIT 2
RESIDENTIAL SURFACE SOILS
TAR CREEK SUPERFUND SITE, OTTAWA COUNTY, OKLAHOMA



Picher Sports Complex - The complex is constructed on a former mine waste site.



Remediated Playground - The playground is located in Picher.