





Navajo Abandoned Uranium Mines NECR-Quivira November 2011 Update

NECR-Quivira Mine


- Located adjacent to the NECR mine site
- Signed Administrative Order on Consent with Rio Algom in 2010





Quivira Mines

- Road paving, fencing and slope stabilization are complete
- Surface soil and deeper (up to 60 feet) soils have been sampled and analyzed
- Current risks are under control but we need to work with the community to evaluate long term solutions



Mariano Lake Mine

- Administrative Order on Consent (AOC) signed with Chevron in July, 2011
- Requires four phases of work:

 Scanning, background study and signage
Fencing
Removal site evaluation
Apply sealant to roads and a large dirt area outside of the mine entrance



Mariano Lake Mine

Mariano Lake Mine

- Once the investigation and work required under the first Order is completed, we will work with the community to decide on future steps
- Any additional response will require a second Order



