

## **MONTROSE – CONSTRUCTION VISIT REPORT**

NAME: YARISSA A MARTÍNEZ-LEÓN

DATE/TIME: July 1, 2013 / 3:29pm until 3:45pm

WEATHER/WIND CONDITIONS: light breeze

Min Temp 65.8°F

Max Temp 86.9 °F Work Area Location:

Javelin St and S New Hampshire Blvd

## **Work Being Performed:**

Please note that the workers were done for the day when I arrived.

However, it was visible in Javelin St and S New Hampshire Blvd that the concrete had been cut to be remove in the pedestrian walkway; and the perimeter of the asphalt was cut for the trench areas on Javelin St.

General Observations: (General Housekeeping, Progress, Health & Safety Procedures)

<u>Javelin St and S New Hampshire Blvd:</u> -Traffic signs were placed and all the areas were secured

Measurement System	
VOC	There was no excavation done on this day
Dust	No exceedence according to daily forms
Noise	No exceedence according to daily forms
Communications:	