

US EPA ARCHIVE DOCUMENT



Guam Waterworks Authority (VP0989)
SDWA Sanitary Survey



Tumon, Guam
Ugum Water Treatment Plant Intake Area
NEIC Field Investigation Photographs
April 25, 2012

Overview Map



US EPA ARCHIVE DOCUMENT

File Name: RIMG0001.JPG



Attributes

Title	Guam Waterworks Authority (VP0989)
Subject	SDWA Sanitary Survey
Latitude	[REDACTED]
Longitude	[REDACTED]
Photo Direction	[REDACTED]
Elevation	[REDACTED]
Date Time Stamp	4/25/2012 10:04:36 AM
Photographer	K. Sable
Comment	Ugum Water Treatment Plant Intake Area
Description	Upstream from intake along Ugum River

File Name: RIMG0002.JPG



Attributes

Title	Guam Waterworks Authority (VP0989)
Subject	SDWA Sanitary Survey
Latitude	[REDACTED]
Longitude	[REDACTED]
Photo Direction	[REDACTED]
Elevation	[REDACTED]
Date Time Stamp	4/25/2012 10:07:48 AM
Photographer	K. Sable
Comment	Ugum Water Treatment Plant Intake Area
Description	At intake showing bamboo blocking algae facing downstream toward dam

File Name: RIMG0003.JPG



Attributes

Title	Guam Waterworks Authority (VP0989)
Subject	SDWA Sanitary Survey
Latitude	██████████
Longitude	██████████
Photo Direction	██████████
Elevation	██████
Date Time Stamp	4/25/2012 10:10:32 AM
Photographer	K. Sable
Comment	Ugum Water Treatment Plant Intake Area
Description	Close-up of intake with screen

File Name: RIMG0004.JPG



Attributes

Title	Guam Waterworks Authority (VP0989)
Subject	SDWA Sanitary Survey
Latitude	██████████
Longitude	██████████
Photo Direction	██████
Elevation	███
Date Time Stamp	4/25/2012 10:17:29 AM
Photographer	K. Sable
Comment	Ugum Water Treatment Plant Intake Area
Description	Hole where old bridge footing was removed, downstream of intake along dam

File Name: RIMG0005.JPG



Attributes

Attributes	
Title	Guam Waterworks Authority (VP0989)
Subject	SDWA Sanitary Survey
Latitude	[REDACTED]
Longitude	[REDACTED]
Photo Direction	[REDACTED]
Elevation	[REDACTED]
Date Time Stamp	4/25/2012 10:19:03 AM
Photographer	K. Sable
Comment	Ugum Water Treatment Plant Intake Area
Description	Facing downstream along dam toward plunge pool

File Name: RIMG0006.JPG



Attributes

Title	Guam Waterworks Authority (VP0989)
Subject	SDWA Sanitary Survey
Latitude	[REDACTED]
Longitude	[REDACTED]
Photo Direction	[REDACTED]
Elevation	[REDACTED]
Date Time Stamp	4/25/2012 10:20:30 AM
Photographer	K. Sable
Comment	Ugum Water Treatment Plant Intake Area
Description	Facing upstream along Ugum River toward dam and intake

File Name: RIMG0007.JPG



Attributes


Title	Guam Waterworks Authority (VP0989)
Subject	SDWA Sanitary Survey
Latitude	██████████
Longitude	██████████
Photo Direction	██████
Elevation	██████
Date Time Stamp	4/25/2012 10:27:21 AM
Photographer	K. Sable
Comment	Ugum Water Treatment Plant Intake Area
Description	Three pumps, two on right in operation (pumps # 1 and # 2) and one on left is out of service (pump # 3)

File Name: RIMG0008.JPG



Attributes

Title	Guam Waterworks Authority (VP0989)
Subject	SDWA Sanitary Survey
Latitude	██████████
Longitude	██████████
Photo Direction	██████████
Elevation	████
Date Time Stamp	4/25/2012 10:28:19 AM
Photographer	K. Sable
Comment	Ugum Water Treatment Plant Intake Area
Description	Close-up of pump # 1 with imbalance



US EPA ARCHIVE DOCUMENT

Attributes	
Title	Guam Waterworks Authority (VP0989)
Subject	SDWA Sanitary Survey
Latitude	[REDACTED]
Longitude	[REDACTED]
Photo Direction	[REDACTED]
Elevation	[REDACTED]
Date Time Stamp	4/25/2012 10:35:26 AM
Photographer	K. Sable
Comment	Ugum Water Treatment Plant Intake Area
Description	Pre-filter information

File Name: RIMG0010.JPG



Attributes

Title	Guam Waterworks Authority (VP0989)
Subject	SDWA Sanitary Survey
Latitude	██████████
Longitude	██████████
Photo Direction	██████
Elevation	███
Date Time Stamp	4/25/2012 10:36:55 AM
Photographer	K. Sable
Comment	Ugum Water Treatment Plant Intake Area
Description	Pre-filters

File Name: RIMG0011.JPG



Attributes

Title	Guam Waterworks Authority (VP0989)
Subject	SDWA Sanitary Survey
Latitude	[REDACTED]
Longitude	[REDACTED]
Photo Direction	[REDACTED]
Elevation	[REDACTED]
Date Time Stamp	4/25/2012 10:40:50 AM
Photographer	K. Sable
Comment	Ugum Water Treatment Plant Intake Area
Description	Turbidimeter on pre-filters



US EPA ARCHIVE DOCUMENT

Attributes

Title	Guam Waterworks Authority (VP0989)
Subject	SDWA Sanitary Survey
Latitude	[REDACTED]
Longitude	[REDACTED]
Photo Direction	[REDACTED]
Elevation	[REDACTED]
Date Time Stamp	4/25/2012 10:41:01 AM
Photographer	K. Sable
Comment	Ugum Water Treatment Plant Intake Area
Description	Close-up of reading on turbidimeter on pre-filters

File Name: RIMG0013.JPG



Attributes

Title	Guam Waterworks Authority (VP0989)
Subject	SDWA Sanitary Survey
Latitude	[REDACTED]
Longitude	[REDACTED]
Photo Direction	[REDACTED]
Elevation	[REDACTED]
Date Time Stamp	4/25/2012 10:41:47 AM
Photographer	K. Sable
Comment	Ugum Water Treatment Plant Intake Area
Description	Flow meter on pre-filters

File Name: RIMG0014.JPG



Attributes

Title	Guam Waterworks Authority (VP0989)
Subject	SDWA Sanitary Survey
Latitude	[REDACTED]
Longitude	[REDACTED]
Photo Direction	[REDACTED]
Elevation	[REDACTED]
Date Time Stamp	4/25/2012 10:45:24 AM
Photographer	K. Sable
Comment	Ugum Water Treatment Plant Intake Area
Description	Back-up generator in control building

File Name: RIMG0015.JPG



Attributes

Title	Guam Waterworks Authority (VP0989)
Subject	SDWA Sanitary Survey
Latitude	██████████
Longitude	██████████
Photo Direction	██████████
Elevation	██████
Date Time Stamp	4/25/2012 10:45:34 AM
Photographer	K. Sable
Comment	Ugum Water Treatment Plant Intake Area
Description	Control panel in control building

File Name: RIMG0016.JPG



Attributes

Title	Guam Waterworks Authority (VP0989)
Subject	SDWA Sanitary Survey
Latitude	██████████
Longitude	██████████
Photo Direction	██████████
Elevation	████
Date Time Stamp	4/25/2012 10:45:49 AM
Photographer	K. Sable
Comment	Ugum Water Treatment Plant Intake Area
Description	Outside control building

File Name: RIMG0017.JPG



Attributes

Title	Guam Waterworks Authority (VP0989)
Subject	SDWA Sanitary Survey
Latitude	██████████
Longitude	██████████
Photo Direction	██████
Elevation	███
Date Time Stamp	4/25/2012 10:51:11 AM
Photographer	K. Sable
Comment	Ugum Water Treatment Plant Intake Area
Description	Diesel fuel tank for generator

File Name: RIMG0018.JPG



Attributes

Title	Guam Waterworks Authority (VP0989)
Subject	SDWA Sanitary Survey
Latitude	[REDACTED]
Longitude	[REDACTED]
Photo Direction	[REDACTED]
Elevation	[REDACTED]
Date Time Stamp	4/25/2012 10:52:51 AM
Photographer	K. Sable
Comment	Ugum Water Treatment Plant Intake Area
Description	Downhill facing diesel fuel tank with Ugum River in background